August 4, 1998




SERVICE BULLETIN

If you have any questions please direct them to the service department 45133 Industrial Dr.
Phone: 650-802-1750
Fremont Ca., 94538
Fax: 650-802-1754


This is to inform you of a possible problem concerning Daytona 2 USA 'DLX versions'.

PROBLEM: Cabinet won't move and/or brake won't disengage.
CAUSE: Incorrect wiring on SSR BD.

SOLUTION: Correct wiring layout on SSR BD should fix problem.



Setup of JST 4 pin plug for low voltage located on SSR BD.



If you have any questions please direct them to the service department at the numbers above.